

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

---

Permit #:PRPWRW20235469, Public Works Right of Way Permit  
Address: 521 SE GRANADA ST, LEES SUMMIT, MO 64063

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Bob Burns	Partial	Monday, November 06, 2023

Corrective Action Required

1	Misc	Site visit, pre pour inspection meets city specs, will need final inspection
---	------	--

**Comments:**