

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20235469, Public Works Right of Way Permit
Address: 521 SE GRANADA ST, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Thad Nave	Passed	Wednesday, November 08, 2023
Corrective Action Required 1 Misc		Site visit, pre pour inspection meets city specs, will need final inspection	
Corrective Action Required 2 Misc		Site visit, final inspection complete, meets ADA requirements	

Comments: