



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20223310, Public Works Right of Way Permit
Address: 4729 NE SARATOGA CT, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Thad Nave	Passed	Wednesday, November 08, 2023
Corrective Action Required			
1	Misc	Site visit, GF drop complete	

Comments: