



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20233379, Public Works Right of Way Permit
Address: 130 NW JOSHUA DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | Inspector: | Outcome: | Date: |
|------------------------------|------------|----------|-----------------------------|
| Site Visit Inspection | Thad Nave | Passed | Thursday, November 16, 2023 |

| Corrective Action Required | |
|----------------------------|------|
| 1 | Misc |

Site visit, Bury service wire complete

Comments: