



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20225152, Public Works Right of Way Permit
Address: 114 NW JOSHUA DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Thad Nave	Passed	Wednesday, November 22, 2023
Corrective Action Required			
1	Misc	Site visit, Bury service wire complete	

Comments: