



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20233374, Public Works Right of Way Permit
Address: 607 NW OLIVE ST, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Thad Nave	Passed	Tuesday, December 12, 2023

Corrective Action Required	
1 Misc	Site visit, Bury service wire complete

Comments: