

Third Party Inspection Report

Inspector	Date	Time								
David P. Ainsworth, P.E.	12-18-23	1:30 PM								
Company	Permit #	Permit Holder								
David P. Ainsworth, P.E.	2023-6294 Address OSAGE LOT 76	CLAYTON PROPERTA								
Inspection Type	Address OSAGE LOT 76									
FOOTING	2116 \$ 2118 SW HOLDBROOKS DR LSMI									
E-Mail Address dainsworth@chelepis.co										
Instructions: This form must be completed when performing a third party inspection for any building										
permit in Lee's Summit. Submit form within 48 hours after inspection to the Development Services										
Department. If a subsequent inspection is performed by the City, this form must be submitted prior to that inspection being scheduled.										
Check all boxes that apply to the site conditions and the inspection being performed.										
Site Conditions:										
Plans stamped by the City on s	ite with the plot plan included. (Co	pied plans are not acceptable)								
Erosion controls in place and n										
*Note: If these requirements are not n	net no inspection shall be performe	d or accepted by the City.								
Foundations and Footings:										
Foundation type and MBOE is	Foundation type and MBOE is equal to or above the plot plan									
Concrete encased electrode (u	Concrete encased electrode (ufer) ground installed (Location must be noted in comments)									
Foundation/Footing meets all engineered design.	Foundation/Footing meets all City Code requirements and matches City approved plans or engineered design.									
Foundation Walls:										
Elevation is sufficient to achiev	re 2% slope away from structure									
No openings below the MBOE										
Concrete encased electrode (u	ıfer) ground exposed									
Foundation wall meets all City engineered design.	Code requirements and matches Ci	ty approved plans or								



-										
H	r	a	ľ	Y	3		r	9	Œ	
		ч	ı		ш	H	ŧ	В	5	•

Framing meets all City Code requirements and matches City approved plans or engineered design.

*Note: Framing can only be covered after mechanical, electrical, and plumbing inspections have been

Corrective Actions and Comments:

UFER GROUND RODS (2) ARE LOCATED

IN THE REAR GARAGE WALL OF EACH

UNIT 4' ON EACH SIDE OF THE

I certify that I have inspected, tested, and checked the work performed, and I find the work to be compliant with all applicable City ordinances and approved building plans and site plans and that the all information in this form is both accurate and true.

Signature: Ward P. Amount P.F. Engineer/Architect Seal