



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20236259, Public Works Right of Way Permit  
Address: 10 NE TUDOR RD, LEES SUMMIT, MO 64086

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Thad Nave	Partial	Wednesday, December 20, 2023

Corrective Action Required	
1      Misc	Site visit, no workers present, will check back

<b>Site Visit Inspection</b>	Thad Nave	Passed	Wednesday, December 20, 2023
------------------------------	-----------	--------	------------------------------

Corrective Action Required	
1      Misc	Site visit, no workers present, will check back

Corrective Action Required	
2      Misc	All work has been completed, No restoration needed, no digging was performed

**Comments:**