



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20232004, Public Works Right of Way Permit
Address: 103 NW JOSHUA DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

| | | | |
|------------------------------|------------|------------------------------|------------------------------|
| Inspection: | Inspector: | Outcome: | Date: |
| Site Visit Inspection | Thad Nave | Passed | Wednesday, December 27, 2023 |
| Corrective Action Required | | | |
| 1 | Misc | Site visit, GF drop complete | |

Comments: