CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

 Permit #:
 PRCOM20225393

 Address:
 801 SW M 150 HWY, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
Underground Electrical Inspection - Commercial		Mitchell Schwarz	Partial	Friday, January 05, 2024	
Informat	ional:				
1	Miscellaneous Correction	Inspected areas Underground for the go the generator passed.	enerator passed. Unde	ed. Underground from the transformer to	
		underground conduit f	underground conduit for light poles S side of building.		
		Underground conduit f	Underground conduit for non permanent power		
		Underground conduit b	Underground conduit between both West most light pole bases		

Comments: