



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20224491, Public Works Right of Way Permit
Address: 432 NW KAYLEA CT, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

| | | | |
|------------------------------|------------|----------|--------------------------|
| Inspection: | Inspector: | Outcome: | Date: |
| Site Visit Inspection | Thad Nave | Passed | Monday, January 08, 2024 |

| | |
|----------------------------|--|
| Corrective Action Required | |
| 1 Misc | Site visit, Bury service wire complete |

Comments: