

## **PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

Permit #:PRPWRW20230587, Public Works Right of Way Permit Address: 4056 NE CHAPEL MANOR DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Site Visit Inspection Thad Nave Passed Friday, January 19, 2024

Corrective Action Required

1 Misc Site visit, GF drop complete

**Comments:**