CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20223975 Address: 204 SW M 150 HWY, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
In-wall Inspection	Kyle Beard	Failed	Wednesday, January 24, 2024

Informational:

1Miscellaneous
CorrectionFreezer south and west walls passed. Okay to insulate those two walls only.1This is just a partial for in wall inspection. This inspection has to fail for
accounting purposes only.

Comments: