## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRRES20221049Address:808 NE ALGONQUIN ST, LEES SUMMIT, MO 64064806 NE ALGONQUIN ST, LEES SUMMIT, MO<br/>64064804 NE ALGONQUIN ST, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: All Rough Inspection - Residential		Inspector:	Outcome:	Date:	
		Khanh Nguyen	Failed	Thursday, January 25, 2024	
Corre	ctive Action Required	:			
1	Misc	-Sister another joist to	804: Have engineer OK/address floor framing underneath master bathroom tub Sister another joist to the notched double joist under front bathroom **or nave engineer address		
		**OK TO ROCK			
		806:			
		-Tie down both ends o door	-Tie down both ends of girder truss to wall **at the other end above entry		
			to address repair for damaged trusses above great room and above set		
		-	ing at bottom wall plate at rear dining		
		-Sister another joist to have engineer addres	hist to the notched double joist under front bathroom **or Idress		
		-	rical above basement ba	athroom shower	
		-Complete framing ar	ound bathroom fan duc	t and fire block walls as required	
		-Provide a receptacle	at hallway outside base	ment bedrooms	
		-Fb sump pump wall f	rom joist space		

-Move GB from rear wall. Provide a receptacle per code

808-OK TO ROCK

Comments: