

Schwerdt Design Group, Inc. 2231 SW Wanamaker, Suite 303 Topeka, KS 66614 Office 785.273.7540

## **Statement of Special Inspections**

| Projec  | t Address: 1020 NW Pryor Rd, Lees Summit, MO 64081 Project Name: 30Hop Streets of West Pryor - Shell Building  |
|---|--|
| In accordance with Chapter 17 of the 2018 International Building Code, and all other applicable codes and referenced standards relevant to the project, the following areas of work require special inspection:   |  |
|   | spection of Wood Construction per 1704.2 and 1705.5 (Shear Walls)  |
|   | spection of Steel Construction per 1704.2 and 1705.2   |
|   | Inspection of Steel per 1705.2   |
|   | Verify materials of high-strength bolts, nuts, and washers   |
|   | Inspection of high-strength bolting  |
| Towns or the last of the last | Verify materials of structural steel   |
|   | Inspection of welding  |
|   | Inspection of steel frame joint details for compliance with approved construction documents  |
|   |  |
|   | Inspection of reinforcing steel, including prestressing tendons and placement  |
|   | Inspection of reinforcing steel welding  |
|   | Inspection of bolts to be installed in concrete prior to and during placement of concrete  |
|   | Verify use of required design mix  |
|   | Sample fresh concrete for slump, air content, and fresh concrete temperature at time of making specimens for strength tests  |
|   | Inspection of concrete and shotcrete placement for proper application techniques   |
|   | Verify specified curing temperature and techniques are maintained  |
|   | Inspection of pre-stressed concrete  |
|   | Inspection of erection of pre-cast concrete  |
|   | Verify in-situ concrete strength, prior to stressing of tendons in post-tensioned concrete and prior to removal of shores and forms from beams and structural slabs          |
|   | Inspection of helical pile foundations   |
|   | Inspection of Masonry per 1705.4   |
|   | Empirically designed masonry, glass unit masonry, and masonry veneer in Risk Category IV   |
|   | Inspection of Wood per 1705.5  |
|   | Inspection of Soil Conditions per 1705.6 and Table 1705.6  |
|   | Inspection of Deep Driven Foundations per 1705.7 and Table 1705.7  |
|   | Inspection of Cast in Place Deep Foundations per 1705.8 and Table 1705.8   |
| 닏   | Inspection of Seismic Resistive Materials per 1705.14  |
| 님   | Inspection of Mastic and Intumescent Fire Resistance Coating per 1705.15   |
| 닏   | Inspection of Fire Resistance Penetrations and Joints per 1705.17  |
| 닏   | Inspection of Smoke Control Systems per 1705.18  |
| Ц   | Other special inspections as required by any adopted code or referenced standard relevant to the project: (Note inspection type and code citations in spaces provided below) |



Schwerdt Design Group, Inc. 2231 SW Wanamaker, Suite 303 Topeka, KS 66614

Office 785.273.7540

Design Professional in Charge:

Prepared By: Schwerdt Design Group, Inc. MICHAEL K. WAMPTON

Design Firm: Schwerdt Design Group, Inc.

Missouri License #: 2008027042

Telephone #: 785-273-7540

Email Address: <u>MKH@sdgarch.com</u>

Signature: \_\_\_\_\_\_ Date: 01/19/24

Seal: