



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20225341, Public Works Right of Way Permit
Address: 621 SW MARRONE DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Passed	Friday, January 26, 2024

Corrective Action Required
1 Misc Site Visit- The drop has been installed.

Comments: