

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20231105  
Address: 800 NW WARD RD, LEES SUMMIT, MO 64086

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Rated Assembly Inspection</b>	Robb Popp	Partial	Thursday, February 01, 2024

Informational:

1	FIRST FLOOR	-Shear wall nailing pattern at stair side of Stair A1 -1st and second layer walls at stair side, Stair A1 -2nd layer on east stair side screw pattern ok -Sheet rock band at floor trusses stair side of Stair B1  -Sheet rock nailing pattern at rim joist 1st and 2nd layer exterior side at elevator A1
---	-------------	---

Informational:

2	SECOND FLOOR	-Shear wall nailing patten and sheet rock band at floor trusses Stair A1 -1st layer at joist space and wall, stair side only, Stair A1
---	--------------	---

Corrective Action Required:

3	THIRD FLOOR
---	-------------

Corrective Action Required:

4	FOURTH FLOOR
---	--------------

**Comments:**