



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20233538, Public Works Right of Way Permit  
Address: 3725 SW WALSH DR, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

| Inspection:                  | Inspector:  | Outcome: | Date:                       |
|------------------------------|-------------|----------|-----------------------------|
| <b>Site Visit Inspection</b> | Matt Munger | Passed   | Thursday, February 01, 2024 |

Corrective Action Required

|   |      |                                                       |
|---|------|-------------------------------------------------------|
| 1 | Misc | Site Visit - The drop appears to have been installed. |
|---|------|-------------------------------------------------------|

**Comments:**