



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20231013, Public Works Right of Way Permit  
Address: 2042 NW OBRIEN RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Thad Nave	Passed	Friday, February 09, 2024

**Corrective Action Required**

1	Misc	Site visit, Appears work has been completed, restoration is still being done, as the location is new home construction and restoration is being done after homes are built
---	------	--

**Comments:**