



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20230478, Public Works Right of Way Permit
Address: 517 SE CARTER RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

| | | | |
|------------------------------|-------------|----------|-----------------------------|
| Inspection: | Inspector: | Outcome: | Date: |
| Site Visit Inspection | Matt Munger | Passed | Thursday, February 22, 2024 |

Corrective Action Required

| | | |
|---|------|--|
| 1 | Misc | Site visit- The drop appears to have been installed. |
|---|------|--|

Comments: