



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20236458, Public Works Right of Way Permit
Address: 520 SE CARTER RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Passed	Thursday, February 22, 2024

Corrective Action Required

1	Misc	Site visit- The drop appears to have been installed.
---	------	--

Comments: