

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20240711, Public Works Right of Way Permit
Address: 305 SW NOEL ST, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Partial	Thursday, February 22, 2024

Corrective Action Required

1 Misc

The plumber used the correct hardback fernco for the connection and chocked in the gravel around the pipe. They grouted around the pipe in the manhole. Originally it was 6" clay they reduced down to 4".

They will be back tomorrow to pour concrete to repair the road.

Comments: