

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20241061
Address: 2136 SW OSAGE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Kyle Beard	Failed	Friday, March 08, 2024

Corrective Action Required:

1	Miscellaneous Correction	-Fire block beam pocket at ceiling in bedroom -Some of furr down ceiling will be below the minimum 6'8" allowable height after sheetrock
---	--------------------------	---

Comments: