



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20230200, Public Works Right of Way Permit

Address: 2003 SW OSAGE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Passed	Monday, March 11, 2024

Corrective Action Required

1	Misc	Site Visit - The drop appears to have been installed.
---	------	---

Comments: