

## **Third Party Inspection Report**

	and makecing yeb	ort
Inspector	Date	Time
David P. Ainsworth, P.E.	3-20-24	1
Company	Permit #	9:30 AM
David P. Ainsworth, P.E.		Permit Holder
Inspection Type	2024-1004 Address	KALKER CUSTOM HOME
FUDTING	Address OF 20	
E-Mail Address	2352 NE WOODGA	ND DAKCIR LSMO
dainsworth@chelepis.com	m	
<b>Instructions:</b> This form must be corpermit in Lee's Summit. Submit form w	npleted when performing a third per	
permit in Lee's Summit. Submit form w Department. If a subsequent inspection	vithin 48 hours after inspection to the	ne Dovolance and S
Department. If a subsequent inspectio that inspection being scheduled.	n is performed by the City, this forn	ne Development Services  n must be submitted prior to
Check all boxes that apply to the site co	nditions and the inspection being p	erformed.
Site Conditions:		
Plans stamped by the City on sit	e with the plot plan included. (Copi	
Erosion controls in place and ma	pintained	ed plans are not acceptable)
*Note: If these requirements are not me	et no inspection shall be performed	or accepted by the City.
oundations and Footings:		
Foundation type and MBOE is eq	ual to or above the plot plan	
Concrete encased electrode (ufe	r) ground installed (Location must b	
Foundation/Footing meets all Cit	v Code remined (Location must p	e noted in comments)
engineered design.	y Code requirements and matches	City approved plans or
oundation Walls:		
Elevation is sufficient to achieve 2	2% slope away from structure	
No openings below the MBOE		
Concrete encased electrode (ufer		
Foundation wall meets all City Cod	de requirements and matches City a	nnroyed plans
engineered design.	and the second of the second o	pproved plans or



Framing:	Fra	mi	ng:
----------	-----	----	-----

Framing meets all City Code requirements and matches City approved plans or engineered design.

\*Note: Framing can only be covered after mechanical, electrical, and plumbing inspections have been passed.

## **Corrective Actions and Comments:**

UFER GROUND ROD IS LOCATED IN THE LEFT SIDEWALL ABOUT 4' BACK OF THE REAR CARAGE WALL,

I certify that I have inspected, tested, and checked the work performed, and I find the work to be compliant with all applicable City ordinances and approved building plans and site plans and that the all information in this form is both accurate and true.

Signature:

Engineer/Architect Seal