



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20241319, Public Works Right of Way Permit  
Address: 1904 SW HIGHTOWN DR, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Matt Munger	Partial	Tuesday, March 26, 2024

**Corrective Action Required**

1      Misc

Site Visit - The crews were out working. They had signs on their trucks. I stopped and spoke to one of the workers and handed out one of our ROW sheets. I will continue to monitor. Most of the work is being done on lots with no houses.

**Comments:**