

## **Third Party Inspection Report**

Inspector	Date	Ι									
David P. Ainsworth, P.E.		Time									
Company	3-14-24	3:00 PM									
	Permit #	Permit Holder									
David P. Ainsworth, P.E.	2024-0626 Address HAWTHORNE	CLAYTON POOREDHEE									
Inspection Type	Address HAWTHORNE	RIDGE 1 AT 171									
FOOTING	3212 SW ARBOR	- SOUND DR LS HO									
E-Mail Address dainsworth@cholonia.acr		, JOHN PR LIMIO									
dainsworth@chelepis.com											
Instructions: This form must be completed when performing a third party inspection for any building permit in Lee's Summit. Submit form within 48 have a few submit f											
Submit 10111 WILLIII 48 Hollrs after inspection to the D											
Department. If a subsequent inspection is performed by the City, this form must be submitted prior to that inspection being scheduled.											
Check all boxes that apply to the site conditions and the inspection being performed.											
Site Conditions:											
Plans stamped by the City on site with the plot plan included. (Copied plans are not acceptable)											
Erosion controls in place and maintained											
*Note: If these requirements are not met no inspection shall be performed or accepted by the City.											
Foundations and Footings:											
	2000 A										
	Foundation type and MBOE is equal to or above the plot plan										
Concrete encased electrode (ufe	Concrete encased electrode (ufer) ground installed (Location must be noted in comments)										
Foundation/Footing meets all Cite engineered design.	ty Code requirements and matches	City approved plans or									
Foundation Walls:											
Elevation is sufficient to achieve	2% slope away from structure										
No openings below the MBOE	, ou deture										
Concrete encased electrode (ufe	r) ground exposed										
	de requirements and matches City a	approved plans or									



F	r	a	r	7	า	i	r	1	a	
	ı	a	ı	ı	ı	ı	ı	ı	x	

Framing meets all City Code requirements and matches City approved plans or engineered design.

\*Note: Framing can only be covered after mechanical, electrical, and plumbing inspections have been

## **Corrective Actions and Comments:**

UPER GROUND ROD IS LOCATED 3 FORWARD OF RIGHT REAR CORNER OF INTERIOR GARAGE WALL.

I certify that I have inspected, tested, and checked the work performed, and I find the work to be compliant with all applicable City ordinances and approved building plans and site plans and that the all information in this form is both accurate and true.

**Engineer/Architect Seal**