

Third Party Inspection Report

Inspector	5										
Sec. (2)	Date	Time									
David P. Ainsworth, P.E.	8-8-23	2:15 PM									
Company	Permit #	Permit Holder									
David P. Ainsworth, P.E.	2073-2518	Capital Co									
Inspection Type	Address PARK PARK	CAPTIAL WNST. >VO									
FOOTING E-Mail Address	4367 ALK HING	LUI 200									
dainsworth@chelepis.cor	n										
Instructions: This form must be compermit in Lee's Summit. Submit form w	npleted when performing a third p	orty income till f									
The substitution of the su	/ILIIII 40 DOIIIS atter increation to 1	L - D									
. a sabsequent hispection	n is performed by the City, this form	n must be submitted prior to									
, and someduicu,											
Check all boxes that apply to the site co	nditions and the inspection being	performed.									
Site Conditions:											
Plans stamped by the City on sit	o with the color of the color										
Fracion control in 1	e with the plot plan included. (Cop	ied plans are not acceptable)									
Erosion controls in place and ma											
*Note: If these requirements are not me	et no inspection shall be performed	or accepted by the City.									
Foundations and Footings:											
Foundation type and MBOE is ed	ual to or above the plot plan										
	r) ground installed (Location must	he noted in commants)									
Foundation/Footing meets all Cit	cy Code requirements and matches	City Comments)									
engineered design.	, and requirements and matches	City approved plans or									
Foundation Walls:											
Elevation is sufficient to achieve	2% slope away from structure										
No openings below the MBOE	, and a structure										
Concrete encased electrode (ufe	r) ground avacced										
engineered design.	de requirements and matches City	approved plans or									
33.6.1											



C	_		_		0			_	
Г	a	I	ı	l	U	ľ	I,	K	

Framing meets all City Code requirements and matches City approved plans or engineered design.

*Note: Framing can only be covered after mechanical, electrical, and plumbing inspections have been

Corrective Actions and Comments:

UFER GROUND ROD IS ON THE LEFT 3102 10' FROM THE FRONT.

I certify that I have inspected, tested, and checked the work performed, and I find the work to be compliant with all applicable City ordinances and approved building plans and site plans and that the all information in this form is both

accurate and true.

Engineer/Architect Seal