

Third Party Inspection Report

Inspector	Date	
David P. Ainsworth, P.E.		Time
Company	4-12-24	1:00 PM
1. (3.00.	Permit #	Permit Holder
David P. Ainsworth, P.E.	2024-1361	CLAYTON PROPERT
Inspection Type	Address HAWTHORNE	RIDGE LOT 175
- FOOTING	3228 SW ARBOR	Sound DD
E-Mail Address dainsworth@chelepis.co		
Instructions: This form must be co	mpleted when performing a third p	party inspection for any building
Department. If a subsequent inspection	within 48 hours after inspection to	the Davolanment Comi
that inspection being scheduled.		
Check all boxes that apply to the site of	onditions and the inspection being	performed.
Site Conditions:		
Plans stamped by the City on s	ite with the plot plan included. (Co	pied plans are not acceptable)
Erosion controls in place and m		
*Note: If these requirements are not m	et no inspection shall be performe	d or accepted by the City.
Foundations and Footings:		, ,
Foundation type and MBOE is e	qual to or above the plot plan	
	er) ground installed (Location must	be noted in comments)
	ity Code requirements and matche	
Foundation Walls:		
Elevation is sufficient to achieve	2% slope away from structure	
No openings below the MBOE	and the second of the second o	
Concrete encased electrode (uf	er) ground exposed	
	ode requirements and matches Cit	y approved plans or



-			40.	
⊩	ra	m	In	O.
	ra			8.

Framing meets all City Code requirements and matches City approved plans or engineered design.

*Note: Framing can only be covered after mechanical, electrical, and plumbing inspections have been passed.

Corrective Actions and Comments:

UFER GROUND ROD IS LOCATED IN THE LEFT SIDEWALL 12' BACK OF THE LEFT FRONT CORNER.

I certify that I have inspected, tested, and checked the work performed, and I find the work to be compliant with all applicable City ordinances and approved building plans and site plans and that the all information in this form is both accurate and true.

Signature: Sar J. amaron

Engineer/Architect Seal