

## **Third Party Inspection Report**

Inspector	Data			
David P. Ainsworth, P.E.	Date	Time		
	4-4-74	1:00 Pm		
Company	Permit #	Permit Holder		
David P. Ainsworth, P.E.	2024-1135	CLAYTON PROPERTIES		
Inspection Type	Address HAWTHORNE	PINCE I - 171		
FOOTING	Address HAWTHORNE RIDGE LOT 121 3249 SWARBORTREE DR LSMO			
dainsworth@chelepis.com				
Instructions: This form must be cor	npleted when performing a third na	arty inspection for any building		
<b>Instructions:</b> This form must be completed when performing a third party inspection for any building permit in Lee's Summit. Submit form within 48 hours after inspection to the Development Services				
repartment. If a subsequent inspection is performed by the City, this form must be submitted and				
and inspection being scrieduled.				
Check all boxes that apply to the site conditions and the inspection being performed.				
Site Conditions:				
Plans stamped by the City on si	to with the alexant of the contract			
Plans stamped by the City on site with the plot plan included. (Copied plans are not acceptable)				
Erosion controls in place and maintained				
*Note: If these requirements are not met no inspection shall be performed or accepted by the City.				
Foundations and Footings:				
Foundation type and MBOE is ed	qual to or above the plot plan			
Concrete encased electrode (ufer) ground installed (Location must be noted in comments)				
Foundation/Footing meets all City Code requirements and matches City approved plans or				
engineered design.	, and requirements and matches	city approved plans or		
Foundation Walls:				
Elevation is sufficient to achieve	2% slope away from structure			
No openings below the MBOE				
Concrete encased electrode (ufer) ground exposed				
Foundation wall meets all City Code requirements and matches City approved plans or engineered design.				



Fra	mi	ng:
-----	----	-----

Framing meets all City Code requirements and matches City approved plans or engineered design.

\*Note: Framing can only be covered after mechanical, electrical, and plumbing inspections have been passed.

## **Corrective Actions and Comments:**

UFER GROUND ROD IS LOGATED 8'OFF BACK LEFT CORNER OF GARAGE ON BACK WALL

I certify that I have inspected, tested, and checked the work performed, and I find the work to be compliant with all applicable City ordinances and approved building plans and site plans and that the all information in this form is both accurate and true.

Signature:

Sand P. amarate P.E.

Engineer/Architect Seal

Development Services
220 SE Green Street | Lee's Summit, MO 64063 | P: 816.969.1200 | F: 816.969.1221 | cityofLS.net