

## **Third Party Inspection Report**

Inspector	Date				
David P. Ainsworth, P.E.	1 - 5 - 5 - 6 - 6 - 6 - 6 - 6 - 6 - 6 - 6	Time			
	4-23-24	1:45 PM			
Company	Permit #	Permit Holder			
David P. Ainsworth, P.E.	2024-1680	CLANTON PROPERTI			
Inspection Type	Address	COMITON TRUTE ICIT			
FOOTING	3220 SW ARBOR SOUND DR LSMG				
L-Wall Address					
dainsworth@chelepis.com					
Instructions: This form must be con	mpleted when performing a third p	arty inspection for any building			
permit in Lee's Summit. Submit form v	vithin 48 hours after inspection to t	he Development Services			
bepartment. If a subsequent inspection is performed by the City, this form must be submitted prior to					
that inspection being scheduled.					
Check all boxes that apply to the site conditions and the inspection being performed.					
Site Conditions:					
Plans stamped by the City on site with the plot plan included. (Copied plans are not acceptable)					
Erosion controls in place and maintained					
*Note: If these requirements are not met no inspection shall be performed or accepted by the City.					
Foundations and Footings:					
Foundation type and MBOE is equal to or above the plot plan					
Concrete encased electrode (ufer) ground installed (Location must be noted in comments)					
Foundation/Footing meets all City Code requirements and matches City approved plans or engineered design.					
-					
Foundation Walls:					
Elevation is sufficient to achieve 2% slope away from structure					
No openings below the MBOE					
Concrete encased electrode (ufer) ground exposed					
Foundation wall meets all City Code requirements and matches City approved plans or engineered design.					



-				
<b>I</b> -1	$r \rightarrow$	m	III	a.
	ıa			g:
				Ο-

Framing meets all City Code requirements and matches City approved plans or engineered design.

\*Note: Framing can only be covered after mechanical, electrical, and plumbing inspections have been passed.

## **Corrective Actions and Comments:**

UFER GROUND ROD IS LOCATED IN THE BACK WALL OF THE GARAGE 12'OFF THE LEFT END OF THE HOUSE.

I certify that I have inspected, tested, and checked the work performed, and I find the work to be compliant with all applicable City ordinances and approved building plans and site plans and that the all information in this form is both

accurate and true.

Signature: Lail Umanon

**Engineer/Architect Seal**