

Third Party Inspection Report

	may mobection kept	אונ			
Inspector	Date	Time			
David P. Ainsworth, P.E.	4-29-24				
Company	Permit #	1 (*, oo Ann Permit Holder			
David P. Ainsworth, P.E.	2024-1800				
Inspection Type	Address OSAGE LOT 69	CLAYTON PROPERTY			
FUDTING	3824 SW ROYENGATE PL LSM 6				
E-Mail Address dainsworth@chelepis.co		ATE IL LIMB			
permit in Lee's Summit. Submit form we Department. If a subsequent inspection that inspection being scheduled.	VILIIII 48 DOIITS atter increation to the	D			
Check all boxes that apply to the site conditions and the inspection being performed.					
Site Conditions:	,	eriormed.			
Erosion controls in place and m					
*Note: If these requirements are not m	et no inspection shall be performed	or accepted by the City.			
Foundations and Footings:					
Foundation type and MBOE is equal to or above the plot plan					
Concrete encased electrode (ufer) ground installed (Location must be noted in comments)					
Foundation/Footing meets all City Code requirements and matches City approved plans or engineered design.					
oundation Walls:					
Elevation is sufficient to achieve	2% slope away from structure				
No openings below the MBOE	many monitoriactare				
Concrete encased electrode (ufe	er) ground exposed				
Foundation wall meets all City Code requirements and matches City approved plans or engineered design.					



F	ra	m	in	g:
				o.

Framing meets all City Code requirements and matches City approved plans or engineered design.

*Note: Framing can only be covered after mechanical, electrical, and plumbing inspections have been passed.

Corrective Actions and Comments:

UFER GROUND ROD LOCATED ON BACK WALL OF GARAGE 8' OFF OF THE LEFT REAR CORNER OF THE GARAGE.

I certify that I have inspected, tested, and checked the work performed, and I find the work to be compliant with all applicable City ordinances and approved building plans and site plans and that the all information in this form is both

accurate and true.

Engineer/Architect Seal