

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20231105
Address: 800 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Robb Popp	Partial	Thursday, May 02, 2024

Informational:

1	FIRST FLOOR	-Shear wall nailing pattern at stair side of Stair A1 -1st and second layer walls at stair side, Stair A1 -2nd layer on east stair side screw pattern ok -Shear wall behind bathtubs building A -Pre rock behind tubs all units building B *Stair 2B: -1st and 2nd layer stringer side only *Stair 3B: -1st and 2nd layer stringer side only *Stair 4B: -1st layer stringer side only
---	-------------	---

Informational:

2	SECOND FLOOR	-Shear wall nailing patten and sheet rock band at floor trusses Stair A1 -1st and 2nd layer at joist space and wall, stair side only, Stair A1 -Pre rock behind tubs all units building B *Stair 2B: -1st and 2nd layer stringer side only
---	--------------	--

Corrective Action Required:	3	THIRD FLOOR	*Stair 3B: -1st and 2nd layer stringer side only
			*Stair 4B: -1st layer stringer side only
			-1st and 2nd layer at wall stair side only Stair A1 -Pre rock behind tubs Building A 1st and 2nd Layer -Pre rock behind tubs all units building B 1st Layer
Informational:	4	FOURTH FLOOR	*Stair 2B: -1st and 2nd layer stringer side only
			*Stair 3B: -1st and 2nd layer stringer side only
			*Stair 4B: -1st layer stringer side only
Informational:	5	Misc	-1st and 2nd layer behind tubs at units -1st and 2nd layer at A/B separation wall at units -Pre rock behind tubs all units building B
			*Stair 1A: -1st and 2nd layer stringer side only -1st layer at joist space and wall, dwelling side, Stair 1A
			*Stair 2B: -1st and 2nd layer stringer side only
Informational:	5	Misc	*Stair 3B: -1st and 2nd layer stringer side only
			**ELEVATOR A1 -Sheet rock nailing pattern at rim joist 1st and 2nd layer exterior side at elevator A1 for trusses
			**Stair tower in building E -Shear wall nailing pattern approved

Comments: