

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20240550

Address: 3734 SW KNOXVILLE CT, LEES SUMMIT, MO 640823736 SW KNOXVILLE CT, LEES SUMMIT, MO  
64082

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Kyle Beard	Failed	Friday, May 17, 2024

Corrective Action Required:

2	Miscellaneous Correction	3736 SW Knoxville. All rough (2)  Fire block top of chase in between the pantry and dining room Gas gauge on system does not work Some Fire blocking missing above basement Ibeam  3734 Fire block to of chase between pantry an dining Fire blocking is missing between the sump pump area and the garage Have engineer address two broken vertical truss members at north assembly wall by the ridge
---	-----------------------------	--

**Comments:**