## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRRES20240573 Address: 3737 SW KNOXVILLE CT, LEES SUMMIT, MO 640823735 SW KNOXVILLE CT, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: All Rough Inspection - Residential		Inspector:	Outcome:	Date:	
		Kyle Beard	Failed	Friday, May 17, 2024	
Correct	ive Action Required:				
2	Miscellaneous Correction	3737 and 3735 SW Knoxville. All rough (2)			
		3737			
		Garage S/E corner is not completed (corners must consist of three studs and bare on the sole plate and up against the top plate)			
		-	Garage to house doors needs electrical next to it to be replaced and secured Fire block hole in entry closet at sole plate		
		•	Have engineer address where ceiling/floor joist have been cut on the ends where attached to the Ibeam in the dining room		
		Electrical at kitcher	Electrical at kitchen wall and above kitchen are not fully installed		
		3735	35		
		Garage North side s foundation wall	Garage North side sole plate does not completely rest on the concrete oundation wall		

Comments: