

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20240550

Address: 3734 SW KNOXVILLE CT, LEES SUMMIT, MO 640823736 SW KNOXVILLE CT, LEES SUMMIT, MO
64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Kyle Beard	Not Ready	Tuesday, May 21, 2024

Corrective Action Required:

1	Miscellaneous Correction	3736 SW Knoxville. All rough (2) Fire block top of chase in between the pantry and dining room (fill gaps around new ceiling plywood that was installed) Gas gauge is still not installed on the system for inspection 3734 Fire block to of chase between pantry an dining (fill gaps around new ceiling plywood that was installed) Fire blocking is missing between the sump pump area and the garage (fill in gap around waste vent PVC) Not ready for inspection
---	--------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Comments: