

Third Party Inspection Report

Inspector	•								
3	Date	Time							
David P. Ainsworth, P.E.	5-21-24	9:45 AM							
Company	Permit #	Permit Holder							
David P. Ainsworth, P.E.	2024-2357	CAMPAN PORPORTING							
Inspection Type	2024-2357 Address HAWTHORNE	LOT 192							
-OUTING	3212 SWARBOR PIDGE CIRLSMO								
E-Mail Address									
dainsworth@chelepis.com									
Instructions: This form must be corpermit in Lee's Summit Submit form	npleted when performing a third na	arty inspection for any build							
. Subliff form	VILIIII 48 NOIIIS after increction to t	h a D							
Department. If a subsequent inspection that inspection being scheduled.	n is performed by the City, this form	n must be submitted prior to							
sale map action being scheduled.									
Check all boxes that apply to the site co	onditions and the inspection being p	performed.							
Site Conditions:									
Plans stamped by the City on si	te with the plot plan included. (Cop	Co. Louis and the control of the con							
Erosion controls in place and m	-interior plot plan included. (Cop	led plans are not acceptable)							
*Note: If these requirements are not mo	et no inspection shall be performed	or accepted by the City.							
Foundations and Footings:									
Foundation type and MBOE is ed	qual to or above the plot plan								
	er) ground installed (Location must	be noted in comments)							
Foundation/Footing meets all Ci	ty Code requirements and matches	City approved also							
engineered design.	, and the control and matches	city approved plans or							
Foundation Walls:									
Elevation is sufficient to achieve	2% slope away from structure								
No openings below the MBOE	, and a started to								
	m)								
Concrete encased electrode (ufe									
Foundation wall meets all City Co engineered design.	de requirements and matches City	approved plans or							



F	ra	31	n	î	n	o	•
ı		10	11	ı	11	×	•

Framing meets all City Code requirements and matches City approved plans or engineered design.

*Note: Framing can only be covered after mechanical, electrical, and plumbing inspections have been passed.

Corrective Actions and Comments:

UFFR GROUND ROD IS LOCATED IN THE SIDEWALL OF THE HOUSE JUST BEHIND THE GARAGE

I certify that I have inspected, tested, and checked the work performed, and I find the work to be compliant with all applicable City ordinances and approved building plans and site plans and that the all information in this form is both accurate and true.

Signature:

Pt. Engin

Engineer/Architect Seal

Sail Chronath,