

## **Third Party Inspection Report**

Inspector	Date								
David P. Ainsworth, P.E.		Time							
Company	5-21-24	11:00 AM							
David P. Ainsworth, P.E.	Permit #	Permit Holder							
Inspection Type	2024-2186 Address HAWTHORNI	CLANTON PROPERTIES							
~	Address 1 Switt ORNI	E 6+120							
FOOTING	3245 SWARBORTREE PRLSMO								
E-Mail Address dainsworth@chelepis.com									
<b>Instructions:</b> This form must be copermit in Lee's Summit. Submit form	mpleted when performing a third pa								
permit in Lee's Summit. Submit form v Department. If a subsequent inspection	within 48 hours after inspection to t	he Development Sarvises							
Department. If a subsequent inspection that inspection being scheduled.	n is performed by the City, this form	n must be submitted prior to							
Check all boxes that apply to the site conditions and the inspection being performed.									
Site Conditions:	,	errormed.							
Plans stamped by the City on si	te with the plot plan included (Con	ied plans are not asset in							
Plans stamped by the City on site with the plot plan included. (Copied plans are not acceptable)  Erosion controls in place and maintained									
*Note: If these requirements are not met no inspection shall be performed or accepted by the City.									
Foundations and Footings:	,	or described by the City.							
Foundation type and MBOE is ed	qual to or above the plot plan								
Concrete encased electrode (ufer) ground installed (Location must be noted in comments)									
Foundation/Footing meets all Ci engineered design.	ty Code requirements and matches	City approved plans or							
Foundation Walls:									
Elevation is sufficient to achieve	2% slope away from structure								
No openings below the MBOE	, and structure								
Concrete encased electrode (ufe	r) ground exposed								
Foundation wall meets all City Code requirements and matches City approved plans or engineered design.									



F	r	a	r	n	i	n	g:
		-	-	٠.			~ ~

Framing meets all City Code requirements and matches City approved plans or engineered design.

\*Note: Framing can only be covered after mechanical, electrical, and plumbing inspections have been passed.

## **Corrective Actions and Comments:**

UFER GROUND ROD IS LOCATED 3'OFF THE BACK CORNER OF THE GARAGE ON THE BACK WALL.

I certify that I have inspected, tested, and checked the work performed, and I find the work to be compliant with all applicable City ordinances and approved building plans and site plans and that the all information in this form is both accurate and true

Cianatura.

Sand P. Chrowal, P.E.

ngineer/Architect Seal