



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20242266, Public Works Right of Way Permit  
Address: 505 SE CARTER RD, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Matt Munger	Partial	Monday, June 03, 2024

Corrective Action Required	
1      Misc	Site Visit - The install work has been completed. I will monitor restoration.

**Comments:**