LEE'S SUMMIT

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20240982, Public Works Right of Way Permit Address: 2772 SW 11TH ST, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Passed	Tuesday, June 18, 2024
Corrective Action Required 1 Misc Site Visit - The work has been completed. Closing.			

Comments: