

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20240021, Public Works Right of Way Permit
Address: 627 NW FAITH DR, Unit:A, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Thad Nave	Passed	Thursday, June 27, 2024

Corrective Action Required

1	Misc	Site visit, Appears water line repair is complete, still needs restoration.
2	Misc	Site visit, site visit, grass is not fully established, will check back
3	Misc	Site visit, Grass is established. Restoration is complete

Comments: