

## **PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

Permit #:PRPWRW20241670, Public Works Right of Way Permit Address: 1928 SW RIVER RUN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Site Visit Inspection Matt Munger Partial Tuesday, July 02, 2024

Corrective Action Required

1 Misc Site Visit - They have the plastic main laid out but are not

boring at this time. Monitoring.

Site Visit Inspection Matt Munger Partial Tuesday, July 02, 2024

Corrective Action Required

1 Misc Site Visit - I spoke with Manny the foreman onsite and I

inquired about depths as they were boring while I was onsite. He stated they were 5ft or greater in most areas from where they started on the north side of SW 26th Street and have gone south on SW 26th Street. Manny did say they were running into rock closer to the area that will need the extra depth. He stated they would need to have different to come into breakup the rock. Currently they are in the 10ft utility easement outside of

ROW.

**Comments:**