

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20240118
Address: 515 NW MOORE ST, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Footing Inspection - Commercial	Robb Popp	Partial	Tuesday, July 02, 2024

Informational:

1	Misc	-Perimeter footing from room 122 north to corner and east to room 134, South from corner to rm 121 -SE corner from stairwell to 111, SW atrium footing to elevator 1 -Interior column pads from 122 north to end of building complete -Elevator 2 mat complete -Elevator 1 mat complete **Ufer location is between 121/119 06/10/24- elevator walls
---	------	---

Comments: