## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20240118 Address: 515 NW MOORE ST, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Footing Inspection - Commercial		Inspector: Robb Popp	Outcome: Partial	Date: Tuesday, July 09, 2024	
					Informa
1	Misc	-Perimeter footing from room 122 north to corner and east to room 134, South from corner to existing building -SE corner from stairwell to 111, SW atrium footing to elevator 1 -Interior column pads from 122 north to end of building complete			
		-Elevator 2 mat com	-Elevator 2 mat complete		
		-Elevator 1 mat complete **Ufer location is between 121/119			
		06/10/24- elevator walls			

**Comments:**