CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20240550 Address: 3734 SW KNOXVILLE CT, LEES SUMMIT, MO 640823736 SW KNOXVILLE CT, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | | Inspector: | Outcome: | Date: |
|---|---|---|--------------------------|-----------------------|
| Occupancy Inspection - Codes Residential | | Kyle Beard | Not Ready | Friday, July 12, 2024 |
| Corrective 1 | Action Required: Miscellaneous Correction | 3734 and 3736 SW Knoxville. Occupancy | | |
| | | ddress numbers are backwards on both units | | |
| | | 3734 Guard rail needs to be installed on the front porch (Northside) First stair riser up from the main floor, has a greater then the code allowed 7 3/4 of an inch Fire block holes in the garage where the walls meet the ceiling Bottom riser in the basement has a riser height of 8 inches Breaker panel is not marked GFCI it's kitchen backsplash does not work | | |
| | | Unit is not ready for inspe inspection | | |
| | | Not a complete list | | |
| | | 3736 Unit has reoccurring defici | encies as the other unit | |

Unit inspection was not conducted

Not a complete list

Not ready for inspection

Comments: