CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20241112 Address: 3731 SW KNOXVILLE CT, LEES SUMMIT, MO 640823729 SW KNOXVILLE CT, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
All Rough Inspection - Residential		Kyle Beard	Not Ready	Monday, July 15, 2024	
Correctiv	e Action Required:				
3	Miscellaneous Correction	3729 and 3731 SW Knoxville. All rough			
		3729			
		Garage 5/8 inch anchor bolts are not located in the middle 1/3 of sole plate and are not tightened down Garage anchor bolts need to be tightened down			
		Nail garage S/W corner to code			
			Fire block holes in top plate in garage		
			ire block top of chase in garage to powder bathroom		
		Fire block 1 3/4 inch waste line in garage horizontal chase			
		Inspection stopped of	nspection stopped due to no fire blocking of both units		
		Walk your property before scheduling inspections			
		Both units are not re Not a complete list	Both units are not ready for inspection Not a complete list		