



CITY OF LEE'S SUMMIT  
CODES ADMINISTRATION  
220 SE GREEN ST.  
P.O.BOX 1600

PHONE:  
816-969-1200

FAX:  
816-969-1201

## Inspection Summary

---

Permit #: PRCOM20110759, Building Permit - Commercial  
Address: 100 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Above Ceiling Inspection</b>	John Borns	Partial	Wednesday, September 21, 2011
Partial Correction 1 MISC		FRAMING & ABOVE-CEILING SYSTEMS @ GWB CEILINGS & SOFFITS: SOFFITS @ 00; 01; 02; 05; 23; 77;	
Partial Correction 2 MISC		CEILING FRAMING & ABOVE-CEILING SYSTEMS AT NORTH ENTRANCE CANOPY OK TO COVER WHEN READY.	
Partial Correction 3 MISC		OK TO COVER WHEN READY EYEBROW SOFFIT/FASCIA FRAMING AT OUTSIDE WALL BORDERING PATIENT ROOMS AT CORRIDORS 18, 30, & 81	
Partial Correction 4 MISC		OK TO COVER WHEN READY ACT CEILING FRAMING & ABOVE-CEILING SYSTEMS AT SPACES: 13; 15; 19; 21; 29; 31; 33A; 33B; 35A; 35B; 38; 40; 25; 27;	
Corrective Action Required 5 MISC		CHECK ALL CEILING SUPPORT WIRES AT SPACES 52-69 TO ENSURE NO LATERAL DEFLECTION BETWEEN UPPER POINT OF ATTACHMENT AND LOWER POINT OF ATTACHMENT	
Corrective Action Required 6 MISC		ELECTRICAL WORK IN PROGRESS AT SPACE 55	
<b>In-wall Inspection</b>	John Borns	Partial	Wednesday, September 21, 2011
Partial Correction 1 MISC		OK TO COVER WHEN READY WALL FRAMING + IN-WALL	

SYSTEMS @ LOCATIONS: 00; 01; 02; 3; 4; 5; 06; 8; 09; 10; 11; 13;  
15; 17; 18; 19; 21; 23; 25; 27; 29; 30; 31; 33A; 35A; 38; 40; PATIENT  
ROOMS 52-69 INCLUDING MEP BUMP-OUTS; 71; 73; 74; 75; 77; 80;  
81; 82; 83; 84; 85; 33B; 35B; S WALL OF 2F082/N WALL OF 2F085;  
WALL ADDED BY PR#3 @ 3F007 WEST -- FULL HEIGHT; FIRE  
WALL AT DOOR OPENING 3F00-A, AROUND OBSTRUCTIONS AND  
TO DECK ABOVE; SMOKE WALL AT CORRIDOR 2A128  
SOUTHEAST

**Comments:**