CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20240573 Address: 3737 SW KNOXVILLE CT, LEES SUMMIT, MO 640823735 SW KNOXVILLE CT, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Occupancy Inspection - Codes Residential		Inspector:	Outcome:	Date:
		Kyle Beard	Failed	Tuesday, July 23, 2024
Corrective	e Action Required:			
2	Miscellaneous Correction			
		3735		
		Fire block gaps in north sid First to second riser going	ding pad not installed at the bottom of the stairway in backyard block gaps in north side chase in garage to second riser going upstairs from the main entry has a greater heigh the code 3/8 of an inch difference (check slope of first riser since	
		3737 Landing pad not installed at the bottom of the stairway in backyard Fire block hole in floor to basement under kitchen island		
		Both units sod, splash pads and sump Deck is missing a joist han Deck joist hanger is missin	-	nstalled
		Final grading needs to be	completed before plot plar	inspection can be

conducted

Pay \$75 fee associated with this permit

Comments: