

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20241323
Address: 1929 SW MERRYMAN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Residential	Kyle Beard	Failed	Thursday, July 25, 2024

Corrective Action Required:

1	Misc	1929 SW Merryman. Occupancy
---	------	-----------------------------

- Front porch needs a guard rail installed facing th East
- Stairwell going down to the basement does not have the required 36 inches of travel distance at the platform

Sod, sump pump extension and splash pads are not installed

Comments: