CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20240118

Address: 515 NW MOORE ST, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Footing Inspection - Robb Popp Partial Monday, July 29, 2024

Commercial

Informational:

1 Misc -Perimeter footing:

North, East footings compleete
West footing from coper to Flevator

West footing from coner to Elevator 1 $\,$

-Interior column pads complete -Interior footings complete

-Elevator 2 mat complete -Elevator 1 mat complete

**Ufer location is between 121/119

-Elevator 1 and 2 walls

Comments: